## BEST AVAILABLE CUTY




FIG.1





FIG. 2



PARALLEL INVERTER SYSTEM
Sandy Ling
WELSH & KATZ, LTD.
Docket No. 92389
Sheet 4 of 9




FIG. 4






FIG. 6

PARALLEL INVERTER SYSTEM Sandy Ling WELSH & KATZ, LTD. Docket No. 92389 Sheet 5 of 9

10/501355



PARALLEL INVERTER SYSTEM
Sandy Ling
WELSH & KATZ, LTD.
Docket No. 92389
Sheet 6 of 9



PARALLEL INVERTER SYSTEM
Sandy Ling
WELSH & KATZ, LTD.
Docket No. 92389
Sheet 7 of 9




FIG.8






FIG.9

10/501355



**FIG.10** 



**FIG.11** 

(

## This Page is Inserted by IFW Indexing and Scanning Operations and is not part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

BLACK BORDERS

INTAGE CUT OFF AT TOP, BOTTOM OR SIDES

FADED TEXT OR DRAWING

BLURRED OR ILLEGIBLE TEXT OR DRAWING

SKEWED/SLANTED IMAGES

COLOR OR BLACK AND WHITE PHOTOGRAPHS

GRAY SCALE DOCUMENTS

LINES OR MARKS ON ORIGINAL DOCUMENT

REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY

## IMAGES ARE BEST AVAILABLE COPY.

**☐** OTHER:

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.